Release note – MultiOne Workflow 3.5.2

In this release the following items were changed (compared to the previous version):

Repaired:

- DC Emergency feature

  For the drivers listed below, only in combination with the mentioned firmware version, the emergency level was configured in the drivers as a percentage value in release 3.5.1.
  In Release 3.5.2 this is repaired and a DALI level (Direct Arc Power Command) is configured.

-

929001408406	Xi FP 75W 0.2-0.7A SNLDAE 230V C133 sXt 1.0
929001408506	Xi FP 75W 0.3-1.0A SNLDAE 230V C133 sXt 1.0
929001408606	Xi FP 75W 0.5-1.5A SNLDAE 230V C133 sXt 1.0
929001522006	Xi FP 100W 0.2-0.7A SNLDAE 230V S240 sXt 1.1
929000976206	Xi FP 165W 0.2-0.7A SNLDAE 230V C170 sXt 1.3
929000976306	Xi FP 165W 0.3-1.0A SNLDAE 230V C170 sXt 1.3
929001408306	Xi FP 330W 2:0.2-0.7A SNDAE C240 sXt 1.0

IMPORTANT NOTICE

1. Before installing, make sure the PC or laptop complies with the minimum system requirements for using MultiOne:
   - PC or laptop with Microsoft Windows 7 SP1, 8, 8.1 and 10
   - One or multiple USB 2.0 or 3.0 port(s):
     - Two free USB ports for use with USB2DALI interface
     - One free USB port for use with USB2ZigBee interface
     - One free USB port for use with SimpleSet interface

     Do check if the USB port is strong enough to power the interface
   - At least 45 MB of free disk space

2. Make sure that also the extra conditions are fulfilled:

- User Software Key on line or off line installed (no action needed if PC already has a key)
- The correct Microsoft Windows version,
  - No Windows XP support
  - When running the installer on Windows 10, a 'Do not run' button might be shown as the application is not signed. Go to 'more info' to force installation.
- If not done yet (not needed if MultiOne 3.2 is already installed): install the version 4.6.1 of Microsoft .NET Framework (This is a Microsoft Windows package that MultiOne need for specific functions.
  - If PC is linked to the internet, and previous version of .NET Framework is available on you system, Microsoft .NET Framework 4.6.1 will be installed (installation takes some extra time)
  - If PC is not linked to the internet, you need to install manually this version on your PC More info and package available on this link https://www.microsoft.com/en-us/download/details.aspx?id=49982 :

Document: 17-07-2017
No: RNW3 2017
Author: B. van der Wijst

©2017 Philips Lighting Holding B.V. All rights reserved. This document contains information relating to the Philips Lighting portfolio, intended for companies who may be interested in developing their product offering. Note that the information provided is subject to change. Philips Lighting does not give any representation or warranty as to the accuracy or completeness of the information included herein and shall not be liable for any action in reliance thereon. The information presented in this document is not intended as any commercial offer and does not form part of any quotation or contract.