



Release note – MultiOne Engineering 3.12

In this release the following items were changed (compared to the previous version):

CHANGES

- 1. Added:
 - Support for new (versions of) LED devices

name	12nc
LDP 100W 1.05A IP67	929002129004
LDP 150W 1.05A IP67	929002129104
LDP 220W 1.05A IP67	929002129204
LDP 65W 1.05A IP67	929002128904
SR Bridge SRB-BS2	929001780413
SR Bridge SRB-LD2	929001780513
Xi BP 22W 0.2-0.7A S 230V C123 sXt	929001499306
Xi BP 40W 0.2-0.7A S 230V C123 sXt	929001499406
Xi BP 40W 0.3-1.0A S 230V C123 sXt	929001499506
Xi FP 150W 0.2-0.7A SNLDAE 230V S240 sXt	929002128606
Xi FP 150W 0.3-1.0A SNLDAE 230V S240 sXt	929002128706
Xi FP 40W 0.2-0.7A SNLDAE 230V S175 sXt	929002128306

Xi FP 75W 0.2-0.7A SNLDAE 230V S240 sXt	929002128406
Xi FP 75W 0.3-1.0A SNLDAE 230V S240 sXt	929002128506
Xi LP 100W 0.3-1.05A S1 230V I175	929002115680
Xi LP 100W 0.3-1.05A S1 230V I175CF	929002115780
Xi LP 100W 0.5-1.5A S1 230V I175	929002115080
Xi LP 100W 0.5-1.5A S1 230V I175CF	929002115280
Xi LP 150W 0.3-1.05A S1 230V I175	929002115480
Xi LP 150W 0.3-1.05A S1 230V I175CF	929002115580
Xi LP 150W 0.5-1.5A S1 230V I175	929002114980
Xi LP 150W 0.5-1.5A S1 230V I175CF	929002115180
Xi LP 22W 0.2-0.7A S1 230V C123 sXt	929002102906
Xi LP 22W 0.3-1.0A S1 230V C123 sXt	929002103006
Xi LP 40W 0.2-0.7A S1 230V C123 sXt	929002103106
Xi LP 40W 0.3-1.0A S1 230V C123 sXt	929002103206
XI030C090V054PST1	929001759113
XI040C110V050VWT1	929001758313
XI075C200V054PST1	929001758413
Xitanium 20W/m 0.15-0.5A 54V TD 230V	929001419006
XJ180C090V285BSF2	929001782113
XJ180C125V200BSF2	929001782213
XJ180C180V144BSF2	929001782313

- New Features:
 - Auxiliary Power Supply
 - Tunable White
- Updated features
 - DTL (Device Temperature Limit): new version is introduced for new drivers:

XJ180C090V285BSF2	929001782113
XJ180C125V200BSF2	929001782213
XJ180C180V144BSF2	929001782313

IMPORTANT NOTICE

Make sure that also the extra conditions are fulfilled:

- User Software Key on line or off line installed (no action needed if PC already has a key)
- Put the *Power mode* of your PC settings in *best performance*.
- The correct Microsoft Windows version,
 - No Windows XP support
 - When running the installer on Windows 10, a 'Do not run' button might be shown as the application is not signed. Go to 'more info' to force installation.

The MultiOne software is tested on a wide variety of virus scanners (latest versions), no issues detected.



Document: 19-06-2019
No: RNE2 2019v2
Author: E. Bos

© Signify NV, 2019. All rights reserved. Signify reserves the right to make changes in specifications and/or to discontinue any product at any time without notice or obligation and will not be liable for any consequences resulting from the use of this publication