



Dimmer Compatibility list

MAS LEDspot LV 11-50W AR111

Transformer														
Brand		Philips						Varilight		OSRAM		Tridonic		
Model		Certaline 60	Certaline 105	Certaline 150	Primaline 70	Primaline 105	Primaline 150	YT50	YT70	HTM 70	HTM 105	VIPER		
Stock		2	7	2	3	2	3	7	2	3	3	5		
Region		EMEA									EMEA			
Without Dimmer		OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK		
Brand	Model	Stock												
Dimmer	Busch Jaeger	6513 U-102	1	OK	OK	OK	Incompatible	Incompatible	OK	OK	OK	Incompatible	Incompatible	Incompatible
	Gira	1176	1	Incompatible	Incompatible	Incompatible	Incompatible	Incompatible	Incompatible	OK	OK	Incompatible	Incompatible	Incompatible
	Merten (Schneider)	5771	1	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
	Insta Group (Berker)	283010	0	OK	OK	Incompatible	Incompatible	Incompatible	Incompatible	OK	Incompatible	Incompatible	OK	Incompatible
	Insta Group (Berker/Insta)	286710/51190	1	OK	OK	OK	OK	OK	Incompatible	OK	OK	Incompatible	OK	OK
	Schneider Electric	315GLE	0	Incompatible	Incompatible	Incompatible	Incompatible	Incompatible	Incompatible	OK	OK	Incompatible	OK	OK

MAS LEDspot LV 15-75W AR111

Transformer														
Brand			Philips				Varilight		OSRAM		Tridonic			
Model			Certaline 60	Certaline 105	Certaline 150	Primaline 70	Primaline 105	Primaline 150	YT50	YT70	HTM 70	HTM 105	VIPER	
Stock			2	7	2	3	2	3	7	2	3	3	5	
Region			EMEA								EMEA			
Without Dimmer			OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Brand	Model	Stock												
Dimmer	Busch Jaeger	6513 U-102	1	OK	OK	OK	OK	Incompatible	Incompatible	OK	OK	Incompatible	Incompatible	Incompatible
	Gira	1176	1	Incompatible	Incompatible	Incompatible	Incompatible	Incompatible	Incompatible	OK	Incompatible	Incompatible	OK	Incompatible
	Merten (Schneider)	5771	1	OK	OK	OK	Fail	OK	OK	OK	OK	OK	OK	OK
	Insta Group (Berker)	283010	0	OK	OK	Incompatible	Incompatible	Incompatible	Incompatible	OK	Incompatible	Incompatible	OK	Incompatible
	Insta Group (Berker/Insta)	286710/51190	1	OK	OK	OK	OK	OK	OK	OK	OK	Incompatible	OK	OK
	Schneider Electric	315GLE	0	Incompatible	OK	OK	Incompatible	Incompatible	Incompatible	OK	OK	Incompatible	OK	OK

MAS LEDspot LV 20-100W AR111

Transformer														
Brand			Philips				Varilight		OSRAM		Tridonic			
Model			Certaline 60	Certaline 105	Certaline 150	Primaline 70	Primaline 105	Primaline 150	YT50	YT70	HTM 70	HTM 105	VIPER	
Stock			2	7	2	3	2	3	7	2	3	3	5	
Region			EMEA								EMEA			
Without Dimmer			OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	
Brand	Model	Stock												
Dimmer	Busch Jaeger	6513 U-102	1	OK	OK	OK	OK	flicker	OK	OK	OK	flicker	OK	OK
	Gira	1176	1	Incompatible	Incompatible	OK	Incompatible	flicker	OK	OK	OK	OK	OK	OK
	Merten (Schneider)	5771	1	OK	OK	OK	Incompatible	OK	Incompatible	OK	OK	OK	OK	OK
	Insta Group (Berker)	283010	0	OK	OK	Incompatible	Incompatible	Incompatible	Incompatible	OK	Incompatible	Incompatible	OK	OK
	Insta Group (Berker/Insta)	286710/51190	1	OK	OK	OK	Incompatible	Incompatible	OK	OK	OK	OK	Incompatible	OK
	Schneider Electric	315GLE	0	OK	Incompatible	Incompatible	Incompatible	Incompatible	OK	OK	OK	OK	OK	OK



© 2017 Philips Lighting. All rights reserved. Reproduction in whole or in part is prohibited without the prior written consent of the copyright owner. The information presented in this document does not form part of any quotation or contract, is believed to be accurate and reliable and may be changed without notice. No liability will be accepted by the publisher for any consequence of its use. Publication thereof does not convey nor imply any license under patent or other industrial or intellectual property rights.

www.philips.com